

Operating instructions | EN

# AS1000

Stepper motors





# 1 Documented motors

AS10xx-xxxx	Holding torque [Nm]	Rated current [A]	Rotor moment of inertia [kg cm <sup>2</sup> ]	Resolution [Steps]	Weight [kg]
AS1010-0000	0,38	1,0	0,056	1,8° / 200 Steps	0,31
AS1020-0xxx	0,5	1,0	0,074		0,39
AS1030-0000	0,6	1,5	0,21		0,68
AS1050-0xxx	1,2	5,0	0,36		1,00
AS1060-xxxx	5,0	5,0	3,0		2,85

# Table of contents

<b>1 Documented motors .....</b>	<b>3</b>
<b>2 Foreword .....</b>	<b>7</b>
2.1 Notes on the documentation .....	7
2.2 Documentation Issue Status .....	8
2.3 Appropriate use .....	9
<b>3 Guidelines and Standards .....</b>	<b>10</b>
3.1 EC Declaration of Conformity .....	10
<b>4 Safety .....</b>	<b>11</b>
4.1 Personnel qualification .....	11
4.2 Description of safety symbols .....	11
4.3 Special safety instructions for AS1000 .....	12
<b>5 Handling .....</b>	<b>13</b>
5.1 Transport .....	13
5.2 Packaging .....	13
5.3 Storage .....	13
5.4 Maintenance / Cleaning .....	14
5.5 Disposal .....	14
<b>6 Product identification .....</b>	<b>15</b>
6.1 AS1000 supply schedule .....	15
6.2 AS1000 name plate .....	15
6.3 AS1000 type key .....	16
<b>7 Technical description .....</b>	<b>17</b>
7.1 Design of the motors .....	17
7.2 General technical data .....	18
7.3 Standard features .....	18
7.3.1 Style .....	18
7.3.2 Shaft end, A-side .....	19
7.3.3 Flange .....	19
7.3.4 Connection technology .....	19
7.3.5 Feedback system .....	19
7.4 Options .....	19
7.5 Transport, assembly and disassembly .....	19
<b>8 Mechanical installation .....</b>	<b>20</b>
8.1 Important notes .....	20
8.2 Installing the stepper motor .....	21
8.3 Installing the incremental encoder (type 2420) .....	21
8.3.1 Technical data of the encoder .....	21
8.4 Planetary gear .....	22
8.4.1 Technical data of the planetary gear units .....	22
8.4.2 Installing the planetary gear .....	22
<b>9 Electrical installation .....</b>	<b>23</b>
9.1 Important notes .....	23

9.2	Connection of motors with preassembled cables.....	24
9.3	Electrical components .....	25
9.3.1	Motor connector .....	25
9.3.2	Encoder connector .....	25
9.4	Connection diagram KL2531 .....	26
9.5	Connection diagram KL2541 .....	27
9.6	Connection diagram EL7031 .....	28
9.7	Connection diagram EL7041 .....	29
9.8	Connection diagram EL7037 .....	30
9.9	Connection diagram EL7047 .....	31
9.10	Connection diagram EP7041-3002 .....	32
<b>10</b>	<b>Commissioning .....</b>	<b>33</b>
10.1	Important notes .....	33
10.2	Guide for commissioning.....	33
10.3	Troubleshooting .....	34
<b>11</b>	<b>Technical data .....</b>	<b>35</b>
11.1	Step mode and limit speeds .....	35
11.2	AS1010-0000 .....	36
11.2.1	Characteristic curve diagram for AS1010-0000 .....	36
11.2.2	Dimensional drawing AS1010-0000 .....	37
11.3	AS1020-0xxx .....	38
11.3.1	Characteristic curve diagram for AS1020-0xxx .....	39
11.3.2	Dimensional drawing AS1020-0xxx .....	40
11.4	AS1030-0000 .....	41
11.4.1	Characteristic curve diagram for AS1030-0000 .....	42
11.4.2	Dimensional drawing AS1030-0000 .....	43
11.5	AS1050-0xxx .....	44
11.5.1	Characteristic curve diagram for AS1050-0xxx .....	45
11.5.2	Dimensional drawing AS1050-0xxx .....	46
11.6	AS1060-xxxx .....	47
11.6.1	Characteristic curve diagram for AS1060-xxxx .....	48
11.6.2	Dimensional drawing AS1060-0xxx .....	49
11.6.3	Dimensional drawing AS1060-1xxx .....	50
<b>12</b>	<b>Support and Service .....</b>	<b>51</b>



## 2 Foreword

### 2.1 Notes on the documentation

This description is only intended for the use of trained specialists in control and automation engineering who are familiar with applicable national standards.

It is essential that the documentation and the following notes and explanations are followed when installing and commissioning the components.

It is the duty of the technical personnel to use the documentation published at the respective time of each installation and commissioning.

The responsible staff must ensure that the application or use of the products described satisfy all the requirements for safety, including all the relevant laws, regulations, guidelines and standards.

#### Disclaimer

The documentation has been prepared with care. The products described are, however, constantly under development.

We reserve the right to revise and change the documentation at any time and without prior announcement.

No claims for the modification of products that have already been supplied may be made on the basis of the data, diagrams and descriptions in this documentation.

#### Trademarks

Beckhoff®, TwinCAT®, TwinCAT/BSD®, TC/BSD®, EtherCAT®, EtherCAT G®, EtherCAT G10®, EtherCAT P®, Safety over EtherCAT®, TwinSAFE®, XFC®, XTS® and XPlanar® are registered trademarks of and licensed by Beckhoff Automation GmbH.

Other designations used in this publication may be trademarks whose use by third parties for their own purposes could violate the rights of the owners.

#### Patent Pending

The EtherCAT Technology is covered, including but not limited to the following patent applications and patents:

EP1590927, EP1789857, EP1456722, EP2137893, DE102015105702

with corresponding applications or registrations in various other countries.



EtherCAT® is a registered trademark and patented technology, licensed by Beckhoff Automation GmbH, Germany

#### Copyright

© Beckhoff Automation GmbH & Co. KG, Germany.

The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization are prohibited.

Offenders will be held liable for the payment of damages. All rights reserved in the event of the grant of a patent, utility model or design.

## 2.2 Documentation Issue Status

### Origin of the document

This documentation was originally written in German. All other languages are derived from the German original.

### Product features

Only the product features specified in the current user documentation are valid. Further information given on the product pages of the Beckhoff homepage, in emails or in other publications is not authoritative.

Issue	Comment
3.7	<b>Chapter update:</b> Documentation Issue Status; EC Declaration of conformity; Safety; Planetary gear; Motor connector; Encoder connector; Connection diagrams
3.6	<b>Chapter update:</b> EC Declaration of conformity; Disposal <b>4.5</b>
3.5	<b>Chapter update:</b> Connection diagram AS1xxx <b>9.4 – 9.10</b>
3.4	<b>Chapter update:</b> Technical data AS1010 – AS1060 <b>11.2 – 11.6</b>
3.3	<b>Chapter update:</b> Foreword 1.0 and Safety 3.0; 2.0
3.2	<b>Chapter update:</b> 7.3.1; 10.1
3.1	<b>New chapter:</b> Documented motors <b>Chapter update:</b> 7.4; 8.3.1; 8.4; 8.5; 8.6; 8.7; 8.8; 8.9; 10.2; 10.3; 10.4; 10.5; 10.6
3.0	<b>General revision</b>
2.2	<b>Chapter revision:</b> <ul style="list-style-type: none"> <li>• Product description – Dimensions</li> <li>• Installation and operation - Installation</li> </ul>
2.1	<b>Chapter revision:</b> <ul style="list-style-type: none"> <li>• Product description – Technical data</li> </ul>

## 2.3 Appropriate use

Stepper motors of the AS1000 series are mainly intended as actuators for handling equipment, textile machines, machine tools, packaging machines and similar machines. The motors of the AS1000 series are **exclusively** intended for operation based on speed and / or position control via stepper motor output stages from Beckhoff Automation GmbH & Co. KG.

### ⚠ CAUTION

#### Danger for persons, the environment or equipment

The motors are operated in the drive system in conjunction with Beckhoff stepper motor output stages. Please observe the entire documentation which consists of:

- AS1000 documentation (this manual)
- Complete documentation (online and paper) for Beckhoff stepper motor output stages available at [www.beckhoff.com](http://www.beckhoff.com).
- Complete machine documentation (provided by the machine manufacturer)

### ⚠ WARNING

#### Caution - Risk of injury!

Electronic equipment is not fail-safe. The machine manufacturer is responsible for ensuring that the connected motors and the machine are brought into a safe state in the event of a fault in the drive system.

#### ● **Special safety instructions for AS1000!**

**i** For the installation and commissioning of the components the observance of the general and special safety instructions [► 12] and explanations is essential. Carefully read the chapters carefully.

The stepper motors from the AS1000 series are designed for installation as components in electrical systems or machines and may be operated only as integrated system or machine components. The motors may **only** be operated under the ambient conditions defined in this documentation.

## 3 Guidelines and Standards

### ⚠ CAUTION

#### **Danger for persons, the environment or equipment**

Stepper motors of the AS1000 series are **not** products as defined by the EC Machinery Directive. Operation of the stepper motors in machines or systems is only permitted once the machine or system manufacturer has provided evidence of CE conformity of the complete machine or system.

### 3.1 EC Declaration of Conformity



#### **Provision of EU Declaration of Conformity:**

Beckhoff Automation GmbH & Co. KG will be glad to provide you with EU declarations of conformity and manufacturer's declarations for all products upon request to [info@beckhoff.com](mailto:info@beckhoff.com).

## 4 Safety

### 4.1 Personnel qualification

This description is only intended for trained specialists in control, automation and drive engineering who are familiar with the applicable national standards.

### 4.2 Description of safety symbols

The following safety symbols and associated safety instructions are used in this document. These safety instructions must be read and followed.

#### **DANGER**

##### **Serious risk of injury!**

Failure to follow the safety instructions associated with this symbol directly endangers the life and health of persons.

#### **WARNING**

##### **Caution – Risk of injury!**

Failure to follow the safety instructions associated with this symbol endangers the life and health of persons.

#### **CAUTION**

##### **Personal injuries!**

Failure to follow the safety instructions associated with this symbol can lead to injuries to persons.

#### **NOTICE**

##### **Damage to the environment or devices!**

Failure to follow the safety instructions associated with this symbol can lead to damage to the environment or equipment.



##### **Tip or pointer**

This symbol indicates information that contributes to better understanding.

## 4.3 Special safety instructions for AS1000

The safety instructions are designed to avert danger and must be followed during installation, commissioning, production, troubleshooting, maintenance and trial or test assemblies. The stepper motors of the AS1000 series are not designed for stand-alone operation and are always installed in a machine or system. After installation, the documentation the documentation and the safety instructions provided by the machine manufacturer must be read and applied.

### **WARNING**

#### **Serious risk of injury through hot surfaces!**

- The surface temperature may exceed 100 °C, resulting in a risk of burns.
- Avoid touching the housing during or shortly after operation.
- Leave the stepper motor to cool down for at least 15 minutes after it is switched off.
- Use a thermometer to check whether the surface has cooled down sufficiently.

### **NOTICE**

#### **Danger for persons, the environment or equipment**

- Please read this manual carefully before using the stepper motor. Follow all safety instructions. If there are sections you do not understand, please contact your sales office and refrain from working with the stepper motor.
- Only well trained, qualified electricians with sound knowledge of drive equipment may work on the device.
- During installation, adhere to the ventilation clearances and climatic conditions. Further information can be found in the "Technical data" and "Mechanical installation" sections.
- If a stepper motor is installed in a machine it must not be commissioned until proof of compliance of the machine with the latest version of the EC Machinery Directive has been provided. This includes all relevant harmonized standards and regulations required for implementation of this Directive in national legislation.

## 5 Handling

### 5.1 Transport

- Climate category: 2K3 according to EN 60721
- Transport temperature: -25 °C - +70 °C, max. fluctuation 20 K/hour
- Transport humidity: relative humidity 5% - 95%, non-condensing
- The stepper motor may only be transported by qualified personnel and in the manufacturer's original recyclable packaging.
- Avoid hard impacts, particularly at the shaft end.
- If the packaging is damaged, check the motor for visible damage. Inform the transport company and, if necessary, the manufacturer.

### 5.2 Packaging

- Cardboard packaging

#### Motor without installed gear unit

Motor type	Max. stacking height
AS1010	5
AS1020	5
AS1030	5
AS1050	5
AS1060	3

#### Motor with installed gear unit

Motor and gear type	Max. stacking height
AS1030 with AG1000-PM052.00x	3
AS1050 with AG1000-PM052.00x	3
AS1060 with AG1000-PM081.00x	2

### 5.3 Storage

- Climate category: 2K3 according to EN 60721
- Storage temperature: -25 °C - +55 °C, max. fluctuation 20 K/hour
- Air humidity: relative humidity 5% - 95%, non-condensing
- Max. stacking height: see table Packaging
- Storage time: without limitation
- Store only in the manufacturer's original recyclable packaging.

## 5.4 Maintenance / Cleaning

- Maintenance and cleaning only by qualified personnel.
- The ball bearings have a grease filling. The actual life of the bearings depends on various factors, including the radial load, shear load, operating temperature and motor speed.
- Check the motor for bearing noise every 2,500 operating hours or once per year. If any noises are heard, stop the operation of the motor. The bearings must be replaced.
- Opening the motor invalidates the warranty.
- Clean the housing with isopropanol or similar.

### NOTICE

#### **Destruction of the stepper motor**

Never immerse or spray the stepper motor.

## 5.5 Disposal

In accordance with the WEEE 2012/19/EU Directives we take old devices and accessories back for professional disposal, provided the transport costs are taken over by the sender.

Send the devices with the note "For disposal" to:

Beckhoff Automation GmbH & Co. KG  
Huelshorstweg 20  
D-33415 Verl

## 6 Product identification

### 6.1 AS1000 supply schedule

Please check that the delivery includes the following items:

- AM1000 series motor
- Connecting cable with 4-pin M12 connector (underside firmly connected)
- Online documentation at [www.beckhoff.de](http://www.beckhoff.de)




#### Scope of supply

The M12 mating connectors are not included!


The following accessories are available on request:

- Second shaft end for AS1020, AS1050 and AS1060
- Encoder with connection cable and 5-pin, screened M12 socket
- Preassembled motor and feedback cable
- Planetary gear, AG1000 series

### 6.2 AS1000 name plate




## 6.3 AS1000 type key



## 7 Technical description

### 7.1 Design of the motors

Beckhoff stepper motors of the AS1000 series are synchronous motors with a large number of poles. They are classified as direct drives. The stepper motors of the AS1000 series are characterized by a high holding torque and very good positioning capability. Thanks to sophisticated control of the stator windings in full-step or micro-step mode, individual steps or partial steps can be executed directly without a feedback system. This feature distinguishes stepper motors from servomotors, thus representing a cost-effective alternative approach. Excessive acceleration and fast load cycles can result in the stepper motor being unable to follow the rotating field and therefore "losing steps". The encoder option can improve matters in this situation.



The stepper motor has its highest torque in the lower speed range. At standstill, the stepper motor is characterized by a very high holding torque. In many applications, this eliminates the need for a holding brake. In the Beckhoff stepper motor terminals a suitable current curve can be stored for any speed or load profile. This serves to optimally adapt the thermal load of the motor. Beckhoff stepper motors are used as actuators or auxiliary axes in machine construction and automation applications. In conjunction with the stepper motor output stages and the Beckhoff TwinCAT automation system, this facilitates integration of cost-effective axes into the overall application. In order to simplify the electrical connection, the stepper motors are equipped with pre-assembled plug connectors. Planetary gear units, incremental encoders and pre-assembled connection cables are available as accessories.

## 7.2 General technical data


Insulation class	Class B (130°C) according to IEC60085
Temperature change at rated current	Max. 80 K
Insulation resistance	≥ 100 MΩ
Permissible ambient temperature (operation)	-10 °C to +50 °C
Permissible ambient temperature (transport/storage)	-25 °C to +70 °C
Permissible air humidity	20% to 90%, non-condensing
Permissible level of contamination	Contamination level 2 according to EN60204/EN50178
Corrosion protection	Under extreme operating conditions, special measures must be agreed with the manufacturer, and implemented by the user.
Permissible operating altitude	Up to 1000 m above sea level
Maximum cable length between motor and terminal	10 m
Special operating conditions	The applicability of the Beckhoff AS1000 stepper motor is to be determined for each individual case. Application in harsh operating or environmental conditions requires coordination between manufacturer and user.
Correct installation position	Horizontal or vertical
Ventilation	Ensure adequate ventilation of the motors.
Protection class (doesn't apply to the shaft bushing)	AS1010 – AS1050: IP43 AS1060: IP20

## 7.3 Standard features

### 7.3.1 Style

The design of the AS1010 and AS1020 stepper motors is intended for flange mounting based on installation types IM B14, IM V18 and IM V19.

The design of the AS1030/AS1050 and AS1060 stepper motors is intended for flange mounting based on installation types IM B5, IM V1 and IM V3.



IM B 5 (B5)  
IM B14 (B14)



IM V 3 (V3)  
IM V19 (V19)



IM V 1 (V1)  
IM V18 (V18)

The permitted mounting positions are specified in the technical data.

### NOTICE

#### Destruction of the motors

Installation positions IM V1 and IM V3 may result in liquid entering the motor and associated damage.

### 7.3.2 Shaft end, A-side

The force transfer is friction-locked (backlash-free), via a clutch, via the cylindrical shaft end A, or optionally as a form-locking connection via a feather key groove according to DIN6885.

#### Radial force

If the motors drive via pinions or toothed belts, then high radial forces will occur.

#### Axial force

Axial forces occur when assembling pinions or pulleys on the shaft.

#### Coupling

Double-coned collets, possibly in association with metal bellows couplings, have proven themselves as excellent, zero backlash coupling elements.

### 7.3.3 Flange

Flange dimensions according to IEC standard, fit j6, accuracy according to DIN 60034-7

Tolerance class: N

### 7.3.4 Connection technology

The motors are equipped with connecting cables (300 mm) and M12 connectors for the power supply and the feedback signals (encoders only).

The mating connectors are not included in the scope of supply. Ready-made extension cables in different lengths are available as accessories.

### 7.3.5 Feedback system

Feedback system	Resolution	Comment
Incremental encoders	200 increments	Only for AS1020/AS1050/AS1060
Incremental encoders	1024 increments	Only for AS1020/AS1050/AS1060

## 7.4 Options

#### Feather key

Only the AS1060 is optionally available with groove and feather key.

## 7.5 Transport, assembly and disassembly

### ⚠ CAUTION

#### Personal injuries!

Protective clothing, protective gloves and safety boots must be worn at all times during transport, assembly and disassembly. Do not step under suspended motors.

The motors of the AS1000 series can be moved without auxiliary equipment.


## 8 Mechanical installation

### 8.1 Important notes

#### NOTICE

##### Destruction of the motors

- Protect the motors from unacceptable stresses. Take care, especially during transport and handling, that components are not bent and that insulation clearances are not altered.
- The site must be free of conductive and aggressive material. For V1/V3-mounting (shaft end upwards), make sure that no liquids can enter the bearings. If an encapsulated assembly is required, please consult our applications department beforehand.
- Ensure unhindered ventilation of the motors and observe the permissible ambient and flange temperatures. For ambient temperatures above 50 °C please consult our applications department beforehand.
- Stepper motors are precision devices. The flange and shaft are especially vulnerable during storage and assembly. It is important to use the locking thread which is provided to tighten up couplings, gear wheels or pulleys and warm up the drive components, where possible. Blows or the use of force will lead to damage to the ball bearings, the shaft, the holding brake and the feedback system.



- Wherever possible, use only backlash-free, frictionally-locking collets or couplings. Ensure correct alignment of the couplings. A displacement will cause unacceptable vibration and the destruction of the ball bearings and the coupling.
- For toothed belts, it is vital to observe the permissible radial forces. An excessive radial load on the shaft will significantly shorten the service life of the motor.
- Avoid axial loads on the motor shaft, as far as possible. Axial loading significantly shortens the service life of the motor and can result in malfunction of the brake.
- In any case, avoid creating a mechanically constrained motor shaft mounting by using a rigid coupling with additional external bearings (e.g. in a gearbox).
- Check compliance with the permitted radial and axial loads  $F_R$  and  $F_A$ . When using a toothed belt drive, the **minimum** permitted diameter of the pinion follows from the equation:


$$d_{\min} \geq \frac{M_0}{F_R} \times 2$$

## 8.2 Installing the stepper motor

When assembling, make sure that the fastening of the stepper motor is not mechanically overdetermined. Avoid warping, particularly when assembling the shaft.

## 8.3 Installing the incremental encoder (type 2420)

If the stepper motor is ordered with the incremental encoder, the motor and the encoder are fitted in the factory. Retrospective installation of the encoder is only possible, if the stepper motor was ordered with a second shaft end and a hole for the locating pin. The locating pin provides torque support and must be secured with industrial adhesive (e.g. Loctite).



### 8.3.1 Technical data of the encoder

Stepper motors are designed for positioning tasks. Beckhoff stepper motors have a step angle of 1.8° (which is 200 steps/rotation). Stepper motor terminals enable each individual step to be approached. This enables positioning without feedback / encoder. The micro-stepping mode of the stepper motor terminal can be used to improve the physical resolution further. This causes the physical resolution to be multiplied by the micro-step factor. The stepping pattern can be adjusted from full steps, through half steps down to 64 micro-steps. It is possible that, when overloaded, a stepper motor cannot keep up with the desired number of steps. This is referred to as the stepper motor "losing steps". It is therefore possible, optionally, to add an incremental encoder. This requires a second shaft end at the stepper motor. For stepper motors with incremental encoder, the stepper motor output stage KL2541 / EL7041 / EL7037 or EP7041-3002 must be used.

Mechanical properties for 200 and 1024 steps per revolution	
Speed	Max. 6,000 rpm
Moment of inertia of the rotor	Approx. $0.1 \times 10^{-6} \text{ kgm}^2$
Starting torque	< 0.01 Nm
Weight	Approx. 0.06 kg
Protection class according to EN 60 529	IP 50 (for flange) IP 64 (for housing)
Working temperature range	-20 °C...+75 °C
Operating temperature range	-20 °C...+80 °C
Shaft	Shaft: Brass Housing: Aluminium
Shock resistance	In accordance with DIN-IEC 68-2-27: 1000 m/s <sup>2</sup> , (6 ms)
Vibration resistance	In accordance with DIN-IEC 06/02/1968: 100 m/s <sup>2</sup> , (10 to 2000 Hz)

Electrical properties for 200 and 1024 steps per revolution	
Output circuit	push-pull
Supply voltage	11 ... 30 V <sub>DC</sub>
Current consumption (no load)	Standard: 45 mA Maximum 150 mA
Permitted load/channel	± 30 mA
Pulse frequency	Max. 200 kHz
Signal level high	Min. UB-3 V
Signal level low	Max. 2,5 V
Rise time tr	Max. 1 µs
Fall time tf	Max. 1 µs
Short-circuit protected outputs	Yes
CE conform	according to EN 61000-6-1, EN 61000-6-2, EN 61000-6-3 and EN 61000-6-4

## 8.4 Planetary gear

Beckhoff offers planetary gears for stepper motors in order to increase the torque or to improve the mass inertia ratio. Stepper motors whose flanges have dimensions of 56 mm or above can be fitted with low-play planetary gears.

### 8.4.1 Technical data of the planetary gear units

	AG1000-+PM052.00x	AG1000-+PM081.00x
Rated torque	4 Nm	20 Nm
Acceleration torque	6 Nm	30 Nm
Gear play	≤ 0,7°	≤ 0,5°
Max. radial power	200 N	400 N
Max. axial power	60 N	80 N
Stepper motors	AS1030 and AS1050	AS1060
Fastening screws	4 x M4	4 x M6
Tightening torque	2.8 Nm	9 Nm

x = ratio 4 (3.7 exactly or 63/17 as a fraction), ratio 7 (6.75 exactly or 27/4 as a fraction)

Gear rim and planet wheels in steel design, straight-toothed. Lubricant Klübersynth GE14-151

### 8.4.2 Installing the planetary gear

If the stepper motor is ordered together with the planetary gear, the motor and the gear unit are fitted in the factory. For retrospective installation please note the following:

- The planetary gear of the AG1000-xxxx series are supplied with a separate adapter shaft and integrated sun wheel.
- Slide the adapter shaft onto the stepper motor shaft up to the end stop and secure it with a heat resistant, industrial adhesive (e.g. Loctite).
- Before applying the adhesive to the adapter shaft clean the motor shaft with a suitable solvent.
- Slide the gear unit onto the adapter shaft. Screw the gear flange to the motor flange. Ensure the screws are tightened evenly to avoid tensions in the component.

## 9 Electrical installation

### 9.1 Important notes

#### **DANGER**

##### **Serious risk of injury through electric shock!**

- Only staff qualified and trained in electrical engineering are allowed to wire up the motor.
- Check the assignment of the stepper motor output stage and the motor. Compare the rated voltage and the rated current of the devices.
- Always make sure that the motors are de-energized during assembly and wiring, i.e. no voltage may be switched on for any piece of equipment which is to be connected. Ensure that the control cabinet remains turned off (barrier, warning signs etc.). The individual voltages will only be turned on again during commissioning.
- Control and power leads may be live, even if the motor is not running.

#### **NOTICE**

##### **Smooth operation**

- Ensure that the motor is grounded properly. See below for further information regarding EMC shielding and earthing. Earth the mounting plate and motor housing.
- Use only cables approved by Beckhoff for use with the AS1000 stepper motors.
- Wiring:
  - ⇒ Connecting the feedback cable (optional)
  - ⇒ Connect the motor cables
  - ⇒ Shielding at both ends (shield terminal or EMC plug)

#### **NOTICE**

##### **HF interference**

- The ground symbol , which you will find in the wiring diagrams, indicates that you must provide an electrical connection, with as large a surface area as possible, between the unit indicated and the mounting plate in the control cabinet. This connection is to suppress HF interference and must not be confused with the PE (protective earth) symbol (protective measure according to EN 60204).

## 9.2 Connection of motors with preassembled cables



Beckhoff offers preassembled motor and feedback cables for safe, faster and flawless installation of the motors. Beckhoff cables have been tested with regard to the materials, shielding and connectors used. They ensure proper functioning and compliance with statutory regulations such as EMC, UL etc. The use of other cables may lead to unexpected interference and invalidate the warranty.


- Carry out the wiring in accordance with the valid standards and regulations.
- Only use our preassembled shielded cables for the power and feedback connections.
- The shielding should match the specifications in sections 8.4 to 8.10. Incorrectly installed shielding inevitably leads to EMC interference.
- The motor connector and the mating connector of the Beckhoff motor cable is a special version with 5 A current-carrying capacity. The use of other M12 connector can lead to overload.

9.3 Electrical components

9.3.1 Motor connector



The stepper motors are equipped with a 300 mm long connection cable and a preassembled M12 connector plug.

Motor winding	Motor connector ZS2000-2610
<div><p>Internal wiring connection</p></div>	

Contact	Color of conductor	Signal	Round connector – 4-pin
1	Red	Phase 1	
2	Yellow	Phase 2	
3	Orange	Phase 3	
4	Blue	Phase 4	

9.3.2 Encoder connector


The optional encoder is equipped with a 300 mm long, screened connection cable and a screened, preassembled M12 connector coupling.

Pin	Color of conductor	Signal	Round connector – 5-pin	Encoder connector
1	White	0 V		
2	Brown	+Ub		
3	Green	Track A		
4	Yellow	Track B		
5	Grey	Track 0		

## 9.4 Connection diagram KL2531

### Stepper motor terminal KL2531

- For AS1010, AS1020 and AS1030 without incremental encoder
- View "X" shows the top view from the connector of the motor cable



### Motor cable ZK4000-6700-2xxx


- Preassembled on both sides, 4 x 0.5 mm<sup>2</sup>, shielded



## 9.5 Connection diagram KL2541

### Stepper motor terminal KL2541

- For AS1020, AS1050 and AS1060 with incremental encoder
- View "X" shows the top view from the connector of the motor cable
- View "Y" shows the top view from the connector of the encoder cable



### Motor cable ZK4000-6700-2xxx

- Preassembled on both sides, 4 x 0.5 mm<sup>2</sup>, shielded



### Encoder cable ZK4000-5100-2xxx


- Preassembled on both sides, 5 x 0.25 mm<sup>2</sup>, shielded



## 9.6 Connection diagram EL7031

### Stepper motor terminal EL7031

- For AS1010, AS1020 and AS1030 without incremental encoder
- View "X" shows the top view from the connector of the motor cable



### Motor cable ZK4000-6700-2xxx


- Preassembled on both sides, 4 x 0.5 mm<sup>2</sup>, shielded



## 9.7 Connection diagram EL7041

### Stepper motor terminal EL7041

- For AS1020, AS1050 and AS1060 with incremental encoder
- View "X" shows the top view from the connector of the motor cable
- View "Y" shows the top view from the connector of the encoder cable



### Motor cable ZK4000-6700-2xxx

- Preassembled on both sides, 4 x 0.5 mm<sup>2</sup>, shielded



### Encoder cable ZK4000-5100-2xxx


- Preassembled on both sides, 5 x 0.25 mm<sup>2</sup>, shielded



## 9.8 Connection diagram EL7037

### Stepper motor terminal EL7037

- For AS1020-0120 with incremental encoder for field-oriented control
- View "X" shows the top view from the connector of the motor cable
- View "Y" shows the top view from the connector of the encoder cable



### Motor cable ZK4000-6700-2xxx

- Preassembled on both sides, 4 x 0.5 mm<sup>2</sup>, shielded




### Encoder cable ZK4000-5100-2xxx

- Preassembled on both sides, 5 x 0.25 mm<sup>2</sup>, shielded



## 9.9 Connection diagram EL7047

- For AS1020-0120, AS1050-0120 and AS1060-0120 with incremental encoder for field-oriented control
- View "X" shows the top view from the connector of the motor cable
- View "Y" shows the top view from the connector of the encoder cable



### Motor cable ZK4000-6700-2xxx

- Preassembled on both sides, 4 x 0.5 mm<sup>2</sup>, shielded



### Encoder cable ZK4000-5100-2xxx


- Preassembled on both sides, 5 x 0.25 mm<sup>2</sup>, shielded



## 9.10 Connection diagram EP7041-3002


### Stepper motor module EP7041-3002

- For AS1xxx with incremental encoder for highspeed applications
- View "X" and "Z" shows the top view from the connector of the motor cable
- View "Y" shows the top view from the connector of the encoder cable




#### Motor cable ZK4000-6768-xxxx

- Preassembled on both sides, 4 x 0.5 mm<sup>2</sup>, shielded



#### Encoder cable ZK4000-5151-xxxx

- Preassembled on both sides, 5 x 0.35 mm<sup>2</sup>, shielded



## 10 Commissioning

### 10.1 Important notes

#### DANGER

##### **Serious risk of injury!**

- Only specialist personnel with extensive knowledge in the areas of electrical engineering / drive technology are allowed to install and commission the equipment.
- The surface temperature of the motor can exceed 100 °C in operation. Check (measure) the temperature of the motor. Wait until the motor has cooled down below 40 °C before touching it.
- Make sure that, even if the drive starts to move unintentionally, no danger can result for personnel or machinery.

#### NOTICE

##### **Overloading of the gear!**

With motor / gear combinations can in case of failure (mechanical blockage of the power train) due to high ratio, the gear will be overloaded.

**To prevent this, make sure that the motor rated torque and the motor peak torque is limited in the servo drive.**

Example:

- Motor rated torque / motor peak torque: 1 Nm / 5 Nm
- Gear rated torque / gear peak torque: 15 Nm / 24 Nm
- Gear ratio:  $i = 10$
- The motor rated torque is not limited. The motor peak torque is limited to 2,4 Nm.

### 10.2 Guide for commissioning

The procedure for commissioning is described as an example.

A different method may be appropriate or necessary, depending on the application of the equipment.

- Check the assembly and orientation of the motor.
- Check the drive components (coupling, gear unit, pulley) for the correct seating and setting (observe the permissible radial and axial forces).
- Check the wiring and connections to the motor and the servo drive. Check that the earthing is correct.
- Check whether the rotor of the motor revolves freely (release the brake, if necessary). Listen out for grinding noises.
- Check that all the required measures against accidental contact with live and moving parts have been carried out.
- Carry out any further tests which are specifically required for your system.
- Now commission the motor according to the commissioning instructions.

## 10.3 Troubleshooting

The following table is to be seen as a “First Aid” box. There can be a large number of different reasons for a fault, depending on the particular conditions in your system. The fault causes described below are mostly those which directly influence the motor.

Our applications department can give you further help with your problems.

Error	Possible cause	Measures to remove the cause of the fault
Motor doesn't rotate	Break in setpoint lead	Check setpoint lead
	Motor phases in wrong sequence	Correct the phase sequence
	Drive is mechanically blocked	Check mechanism
Motor runs away	Motor phases in wrong sequence	Correct the phase sequence
Motor oscillates	Break in the shielding of the feedback cable	Replace the feedback cable
	Amplification to high	Use motor default values
Error message: output stage fault	Motor cable has short circuit or earth leakage	Replace motor cable
	Motor has short circuit or earth leakage	Replace motor
Error message: feedback	Connector is not properly plugged in	Check the plug connector
	Break in cable, cable crushed or similar	Check cables

# 11 Technical data

All data valid for 40 °C ambient temperature and 100 K overtemperature of the winding. The data can have a tolerance of +/- 10%.

If a gear unit is attached the power may be reduced by up to 20 %. This loss in performance has thermal reasons, since a gear unit that is subject to warming is installed at the motor flange intended for heat dissipation.

## Term definitions

### Holding torque $M_H$ [Nm]

The holding torque states the torque that the energized motor can hold at standstill without causing continuous rotation of the rotor.

### Rotor moment of inertia $J$ [kgcm<sup>2</sup>]

The constant  $J$  is a measure of the acceleration capability of the motor. For instance, at  $I_0$  the acceleration time  $t_b$  from 0 to 3000 rpm is given as:

$$t_b [S] = \frac{3000 \times 2\pi}{M_0 \times 60s} \times \frac{m^2}{10^4 \text{ cm}^2} \times J \quad \text{with } M_0 \text{ in Nm and } J \text{ in kgcm}^2$$

### Winding inductance $L$ [mH]

The winding inductance indicates the motor inductance. It is the average value for one motor revolution, with two energized phases, at 1 kHz. Saturation of the motor must be taken into account.

## 11.1 Step mode and limit speeds

The Beckhoff stepper motor terminals are capable of approx. 125,000 steps per second. Beckhoff stepper motors have a step angle of 1.8° or 200 steps per revolution.

Step mode	Limit speed [rpm]
Full step	37.500 (theoretical)
1/2	18.750 (theoretical)
1/4	9.375 (theoretical)
1/8	4,688 (theoretical)
1/16	2.344
1/32	1,171
1/64	585

In practice, the design and construction of the stepper motor limit the maximum speed of rotation. Normally, stepper motors are in fact only used for applications with rated rotation speeds well below 1000 per minute.

## 11.2 AS1010-0000

Technical data	Symbol [Unit]	AS1010
Rated supply voltage	$V_{DC}$	24 – 50
Rated current	A	1,0
Rated power	W	8,4
Holding torque	$M_H$ [Nm]	0,38
Winding resistance Ph-Ph	$R_{20}$ [ $\Omega$ ]	4,10
Winding inductance Ph-Ph	L [mH]	9,50
Rotor moment of inertia	J [kg cm <sup>2</sup> ]	0,056
Resolution	[steps]	1.8° / 200 full steps
Weight	[kg]	0.31
Cogging torque	$M_r$ [Nm]	0.014 ~ 0.016


Mechanical data	Symbol [Unit]	AS1010
Axial load	[N]	10
Radial load 0 mm from the shaft end	[N]	22
Radial load 5 mm from the shaft end	[N]	26
Radial load 10 mm from the shaft end	[N]	33
Radial load 15 mm from the shaft end	[N]	46
Backlash at standstill	[°]	± 0,09
Axial backlash max. <sup>1)</sup>	[mm]	0,075
Radial backlash max. <sup>2)</sup>	[mm]	0,025
Bearing life	[h]	30.000

1) measured at a load of 4.4 N (AS1010 / AS1020)

2) measured at a load of 4.4 N


### 11.2.1 Characteristic curve diagram for AS1010-0000

#### Charakteristische Kurven des AS1010



**11.2.2      Dimensional drawing AS1010-0000**

AS1010-0000



## 11.3 AS1020-0xxx

Technical data	Symbol [Unit]	AS1020
Rated supply voltage	$V_{DC}$	24 – 50
Rated current	A	1,0
Rated power	W	10,0
Holding torque	$M_H$ [Nm]	0,5
Winding resistance Ph-Ph	$R_{20}$ [ $\Omega$ ]	4,80
Winding inductance Ph-Ph	L [mH]	9,50
Rotor moment of inertia	J [kg cm <sup>2</sup> ]	0,074
Resolution	[steps]	1.8° / 200 full steps
Weight	[kg]	0,39
Cogging torque	$M_r$ [Nm]	0.019 ~ 0.023


Mechanical data	Symbol [Unit]	AS1020
Axial load	[N]	10
Radial load 0 mm from the shaft end	[N]	22
Radial load 5 mm from the shaft end	[N]	26
Radial load 10 mm from the shaft end	[N]	33
Radial load 15 mm from the shaft end	[N]	46
Backlash at standstill	[°]	± 0,09
Axial backlash max. <sup>1)</sup>	[mm]	0,075
Radial backlash max. <sup>2)</sup>	[mm]	0,025
Bearing life	[h]	30.000

1) measured at a load of 9 N

2) measured at a load of 4.4 N


### 11.3.1 Characteristic curve diagram for AS1020-0xxx

#### Charakteristische Kurven des AS1020




## 11.3.2 Dimensional drawing AS1020-0xxx


AS1020-0000



AS1020-0100



AS1020-0110



## 11.4 AS1030-0000

Technical data	Symbol [Unit]	AS1030
Rated supply voltage	$V_{DC}$	24 – 50
Rated current	A	1,5
Rated power	W	19,5
Holding torque	$M_H$ [Nm]	0,6
Winding resistance Ph-Ph	$R_{20}$ [ $\Omega$ ]	0,80
Winding inductance Ph-Ph	L [mH]	3,80
Rotor moment of inertia	J [kg cm <sup>2</sup> ]	0,21
Resolution	[steps]	1.8° / 200 full steps
Weight	[kg]	0,68
Cogging torque	$M_r$ [Nm]	0.029 ~ 0.032


Mechanical data	Symbol [Unit]	AS1030
Axial load	[N]	15
Radial load 0 mm from the shaft end	[N]	52
Radial load 5 mm from the shaft end	[N]	65
Radial load 10 mm from the shaft end	[N]	85
Radial load 15 mm from the shaft end	[N]	123
Backlash at standstill	[°]	± 0,054
Axial backlash max. <sup>1)</sup>	[mm]	0,075
Radial backlash max. <sup>2)</sup>	[mm]	0,025
Bearing life	[h]	30.000

1) measured at a load of 9 N


2) measured at a load of 4.4 N

### 11.4.1 Characteristic curve diagram for AS1030-0000

#### Charakteristische Kurven des AS1030



11.4.2      Dimensional drawing AS1030-0000  
AS1030-0000



## 11.5 AS1050-0xxx

Technical data	Symbol [Unit]	AS1050
Rated supply voltage	$V_{DC}$	24 - 50
Rated current	A	5,0
Rated power	W	27,5
Holding torque	$M_H$ [Nm]	1,2
Winding resistance Ph-Ph	$R_{20}$ [ $\Omega$ ]	0,28
Winding inductance Ph-Ph	L [mH]	0,86
Rotor moment of inertia	J [kg cm <sup>2</sup> ]	0,36
Resolution	[steps]	1.8° / 200 full steps
Weight	[kg]	1,00
Cogging torque	$M_r$ [Nm]	0.046 ~ 0.058


Mechanical data	Symbol [Unit]	AS1050
Axial load	[N]	15
Radial load 0 mm from the shaft end	[N]	52
Radial load 5 mm from the shaft end	[N]	65
Radial load 10 mm from the shaft end	[N]	85
Radial load 15 mm from the shaft end	[N]	123
Backlash at standstill	[°]	± 0,054
Axial backlash max. <sup>1)</sup>	[mm]	0,075
Radial backlash max. <sup>2)</sup>	[mm]	0,025
Bearing life	[h]	30.000

1) measured at a load of 9 N

2) measured at a load of 4.4 N


## 11.5.1 Characteristic curve diagram for AS1050-0xxx

### Charakteristische Kurven des AS1050




## 11.5.2 Dimensional drawing AS1050-0xxx


AS1050-0000



AS1050-0100



AS1050-0110



## 11.6 AS1060-xxxx

Technical data	Symbol [Unit]	AS1060
Rated supply voltage	$V_{DC}$	24 – 50
Rated current	A	5,0
Rated power	W	68,8
Holding torque	$M_H$ [Nm]	5,0
Winding resistance Ph-Ph	$R_{20}$ [ $\Omega$ ]	0,36
Winding inductance Ph-Ph	L [mH]	2,80
Rotor moment of inertia	J [kg cm <sup>2</sup> ]	3,0
Resolution	[steps]	1.8° / 200 full steps
Weight	[kg]	2,85
Cogging torque	$M_r$ [Nm]	0.147 ~ 0.215


Mechanical data	Symbol [Unit]	AS1060
Axial load	[N]	60
Radial load 0 mm from the shaft end	[N]	191
Radial load 5 mm from the shaft end	[N]	234
Radial load 10 mm from the shaft end	[N]	301
Radial load 15 mm from the shaft end	[N]	421
Backlash at standstill	[°]	± 0,09
Axial backlash max. <sup>1)</sup>	[mm]	0,075
Radial backlash max. <sup>2)</sup>	[mm]	0,025
Bearing life	[h]	30.000

1) measured at a load of 9 N




2) measured at a load of 4.4 N

## 11.6.1 Characteristic curve diagram for AS1060-xxxx

### Charakteristische Kurven des AS1060



## AS1060-0000





## 12 Support and Service

Beckhoff and their partners around the world offer comprehensive support and service, making available fast and competent assistance with all questions related to Beckhoff products and system solutions.

### Download finder

Our [download finder](#) contains all the files that we offer you for downloading. You will find application reports, technical documentation, technical drawings, configuration files and much more.

The downloads are available in various formats.

### Beckhoff's branch offices and representatives

Please contact your Beckhoff branch office or representative for [local support and service](#) on Beckhoff products!

The addresses of Beckhoff's branch offices and representatives round the world can be found on our internet page: [www.beckhoff.com](http://www.beckhoff.com)

You will also find further documentation for Beckhoff components there.

### Beckhoff Support

Support offers you comprehensive technical assistance, helping you not only with the application of individual Beckhoff products, but also with other, wide-ranging services:

- support
- design, programming and commissioning of complex automation systems
- and extensive training program for Beckhoff system components

Hotline: +49 5246 963-157  
e-mail: [support@beckhoff.com](mailto:support@beckhoff.com)

### Beckhoff Service

The Beckhoff Service Center supports you in all matters of after-sales service:

- on-site service
- repair service
- spare parts service
- hotline service

Hotline: +49 5246 963-460  
e-mail: [service@beckhoff.com](mailto:service@beckhoff.com)

### Beckhoff Headquarters

Beckhoff Automation GmbH & Co. KG

Huelshorstweg 20  
33415 Verl  
Germany

Phone: +49 5246 963-0  
e-mail: [info@beckhoff.com](mailto:info@beckhoff.com)  
web: [www.beckhoff.com](http://www.beckhoff.com)



More Information:  
**[www.beckhoff.com/as1000](http://www.beckhoff.com/as1000)**

Beckhoff Automation GmbH & Co. KG  
Hülshorstweg 20  
33415 Verl  
Germany  
Phone: +49 5246 9630  
[info@beckhoff.com](mailto:info@beckhoff.com)  
[www.beckhoff.com](http://www.beckhoff.com)

